Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-613755
Estimate date:	10-22-23
Customer:	Crystal Murphy
Phone:	832-555-6947
Insurance claim:	C-1465
Vehicle:	2014 Kia Sorento
VIN:	714Y9U4W2TJ4U6851
License plate:	BKR4451

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,971.08
Right front door shell	1	$1,507.71
Front bumper cover	1	$1,299.24
Body labor	38.7 hrs	$2,633.36
Paint and materials		$1,685.53
TOTAL		$9,096.92

Appraiser remarks

Inspection of the driver's side shows a crushed rear quarter panel, a sprung rear door, and a cracked rear window frame, with scuffing that runs along the lower sill. Most of this damage lines up with the side impact described at the intersection. The repair plan calls for replacing the rear door shell, straightening the quarter panel, and refinishing the affected panels to match. The labor hours requested fit the extent of the damage. The invoices submitted show no repeated charges. No earlier damage to the vehicle is known from the records reviewed, and the estimate is recommended for approval.