Freeman Collision Center

4948 Zachary Field Apt. 367
Sugar Land, TX
Phone 346-555-7701

Repair Estimate

Estimate number:	EST-979104
Estimate date:	15 Jan 2025
Customer:	Karen Smith
Phone:	832-555-0027
Insurance claim:	C-1467
Vehicle:	2022 Toyota Camry
VIN:	4TYF19T97ESG40563
License plate:	

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$754.61
Hood panel	1	$653.54
Left quarter panel	1	$438.78
Body labor	28.0 hrs	$1,907.26
Paint and materials		$1,050.07
TOTAL		$4,804.26

Appraiser remarks

Appraiser's remarks: The vehicle arrived with damage to the front bumper cover, left headlamp assembly, hood leading edge and left fender, consistent with a frontal impact during a left turn. Some of the lower radiator support damage may or may not stem from this event, so that area should be confirmed before parts are ordered. The repair plan calls for replacing the bumper cover and headlamp, straightening and refinishing the hood and fender, and reviewing the radiator support on teardown. No prior damage to the vehicle is known. Labor hours are in line with the work described, and the invoices show no duplicate charges.