Mason Collision Center

90659 Johnson Forks Apt. 490
Pearland, TX
Phone 346-555-8742

Repair Estimate

Estimate number:	EST-433862
Estimate date:	08/06/2023
Customer:	Carl Ho
Phone:	832-555-6333
Insurance claim:	C-1471
Vehicle:	2017 Jeep Cherokee
VIN:	4FAAJZ5F2VHNP6043
License plate:	M39 4NY

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,024.46
Left quarter panel	1	$923.22
Right front door shell	1	$471.74
Body labor	26.1 hrs	$1,772.59
Paint and materials		$1,074.52
TOTAL		$5,266.53

Appraiser remarks

Appraiser's remarks: The right rear quarter panel and rear bumper cover show scuffing, a cracked corner of the cover, and a dented fender edge consistent with a sideswipe during a lane change. Parts of the lower rear door show paint transfer that may or may not stem from this event, so I have noted those areas for closer review at teardown. No earlier damage to this vehicle is known from the file. The proposed plan replaces the bumper cover, refinishes the quarter panel, and repairs the fender edge. The labor hours requested fit the scope of the damage described, and the supplied invoices show no repeated charges.