Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-351701
Estimate date:	4-8-24
Customer:	Andrea Taylor
Phone:	346-555-9254
Insurance claim:	C-1472
Vehicle:	2024 Kia Sorento
VIN:	L1RT286S0N76N5586
License plate:	3555

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,131.12
Right front door shell	1	$926.13
Left quarter panel	1	$870.16
Body labor	22.9 hrs	$1,557.98
Paint and materials		$1,020.82
TOTAL		$5,506.21

Appraiser remarks

Inspection of the struck vehicle confirms damage consistent with the side impact reported at the intersection. The crushed rear quarter panel, bent rear door frame, and cracked taillight assembly line up with the direction and force described, and the pattern shows no sign of seaprate prior incidents. The proposed repair plan covers panel replacement, frame straightening, paint blending, and light assembly replacement. Labor hours requested fit the scope of this work. The invoices submitted contain no repeated line items or duplicate charges, and no earlier damage to this vehicle is on record. Recommend approval of the estimate as written.