# Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-486655 |
| **Estimate date:** | 4-19-23 |
| **Customer:** | Billy Jones |
| **Phone:** | 832-555-0948 |
| **Insurance claim:** | C-1473 |
| **Vehicle:** | 2014 Toyota Camry |
| **VIN:** | V1YTRXKM6FNWZ3343 |
| **License plate:** | 1O BY180 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Left front fender | 1 | $1,686.37 |
| Front bumper cover | 1 | $1,293.81 |
| Hood panel | 1 | $1,053.44 |
| Body labor | 49.2 hrs | $3,345.96 |
| Paint and materials | | $1,793.29 |
| TOTAL | | $9,172.87 |

### Appraiser remarks

The left rear quarter panel and rear door show crumpling consistent with a side impact at the described angle, and the pattern of damage fits the account given. Structural measurements show the frame is sound, and no prior damage to the vehicle is known from the records reviewed. The repair plan covers panel replacement, refinishing, and recalibration of the affected sensors, and the labor hours listed are in line with the work required. Two similar chagres submitted on the same day are still under review and will be addressed before final approval.