Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-686257
Estimate date:	10-30-23
Customer:	Jennifer Johnson
Phone:	713-555-9317
Insurance claim:	C-1474
Vehicle:	2010 Toyota Camry
VIN:	4JAMR1C29MZYB2930
License plate:	ZAY 752

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$696.01
Front bumper cover	1	$797.91
Hood panel	1	$616.98
Body labor	24.3 hrs	$1,653.08
Paint and materials		$598.08
TOTAL		$4,362.06

Appraiser remarks

Inspection of the front end shows a crushed radiator support, cracked bumper cover, and a bent hood latch, all consistent with a frontal strike at low speed. The damage pattern lines up with the reported impact, and no older damage or prior repairs are evident on the panels or underlying structure. The proposed plan calls for replacing the bumper cover, hood latch, and radiator support, with painting and refinishing of the adjoining panels. The labor hours requested fit the scope of this work, and the invoices reviewed show no duplicated line items. Recommend approval of the repair as written.