Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-746582
Estimate date:	10/10/2024
Customer:	Allen Murray
Phone:	
Insurance claim:	C-1475
Vehicle:	2023 Kia Sorento
VIN:	EZ1BM0507SHP60041
License plate:	487 LSM

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$976.44
Left quarter panel	1	$910.11
Front bumper cover	1	$725.04
Hood panel	1	$976.44
Body labor	29.9 hrs	$2,031.44
Paint and materials		$1,074.18
TOTAL		$6,693.65

Appraiser remarks

The front bumper cover, radiator support and both headlamp assemblies show crush and fracture patterns that line up with a low-speed frontal impact, and the hood latch area has the expected deformation. Nothing on the vehicle points to older damage, and the proposed repair plan covers replacing the cracked and bent components and refinishing the adjoining panels. The labor hours are in line with the work described. One billing issue needs attention: a single service appears twice on the same day, and the shop has confirmed the second entry was a duplicate and should be removed before the estimate is finalized.