Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-702626
Estimate date:	12-10-23
Customer:	Rachel Stark
Phone:	832-555-8889
Insurance claim:	C-1480
Vehicle:	2019 Honda Civic
VIN:	H98RN2ZH4ERGS7939
License plate:	10UN960

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$466.40
Right front door shell	1	$433.71
Headlamp assembly	1	$382.01
Body labor	12.8 hrs	$867.08
Paint and materials		$357.20
TOTAL		$2,506.40

Appraiser remarks

The vehicle shows damage to the left front quarter panel, front bumper cover and the left headlamp assembly, which lines up well with a side impact during a left turn. The panel crush and paint transfer follow the path described in the account. Repair labor hours are reasonable for the scope of work listed, and the parts and charges on the invioce do not repeat any line item. No prior damage to this vehicle has been identified in our records or during inspection. Recommend proceeding with the repair plan as written, with replacement of the bumper cover and headlamp and refinishing of the fender.