Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-818137
Estimate date:	8-27-23
Customer:	Susan Ramirez
Phone:	
Insurance claim:	C-1483
Vehicle:	2017 Toyota Camry
VIN:	S5NAL2663VL2K7798
License plate:	W62 2BA

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$568.31
Headlamp assembly	1	$502.44
Front bumper cover	1	$403.57
Body labor	11.7 hrs	$794.68
Paint and materials		$440.54
TOTAL		$2,709.54

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact, including the bumper cover, grille, hood leading edge and the radiator support bracket. The repair plan calls for replacing the bumper cover and grille, straightening the hood edge, and refinishing the affected panels. Labor hours are in line with the damage shown. Billing lines were reviewed and no charges appear more than once. An inspection photo on file shows a dent in the same area before this loss, so the prior damage will be separated out from the current repair scope before the estimate is finalized.