Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-719725
Estimate date:	2025-01-06
Customer:	Destiny Smith
Phone:	832-555-5206
Insurance claim:	C-1489
Vehicle:	2023 Hyundai Elantra
VIN:	ZD6DAXNYXV86H0340
License plate:	LJH-627

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$306.12
Left front fender	1	$245.65
Front bumper cover	1	$170.57
Body labor	9.6 hrs	$651.55
Paint and materials		$374.05
TOTAL		$1,747.94

Appraiser remarks

The rear quarter panel and bumper cover show the bulk of the damage, which matches the impact described for a collision during a left turn. Crush depth and paint transfer are consistent with the reported contact point, and no prior damage has been identified on the vehicle. The labor hours on the estimate fit the scope of the repairs. Two similar charges posted on the same day are currently under review before final approval. Recommended plan: replace the bumper cover, repair and refinish the quarter panel, and recheck alignment of the rear suspension components before the vehicle is released.