Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-811404
Estimate date:	9-28-23
Customer:	Matthew Clark
Phone:	713-555-0261
Insurance claim:	C-1492
Vehicle:	2012 Kia Sorento
VIN:	GUBR4NKM5ASX82190
License plate:	047 RZI

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,280.71
Left front fender	1	$1,495.99
Left quarter panel	1	$1,001.53
Body labor	38.7 hrs	$2,629.23
Paint and materials		$1,511.29
TOTAL		$7,918.75

Appraiser remarks

The rear quarter panel and left rear bumper cover show fresh crumpling and paint transfer that line up well with the impact described by the driver during a left-hand turn. Some older scratches sit higher on the same door, and these may predate this loss, so they are noted separately and excluded from the repair scope. The proposed plan replaces the bumper cover, repairs and refinishes the quarter panel, and recalibrates the rear sensor. The labor hours requested fit the extent of the damage, and the invoices submitted reflect a single set of charges with no repeated line items. Recommend approval of the repair as written.