Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-876190
Estimate date:	09/19/2023
Customer:	Tina Woods
Phone:	832-555-1612
Insurance claim:	C-1496
Vehicle:	2018 Nissan Altima
VIN:	5L25TTJ69PYMR5099
License plate:	134315

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$727.71
Hood panel	1	$456.20
Left front fender	1	$419.16
Body labor	18.1 hrs	$1,231.55
Paint and materials		$529.90
TOTAL		$3,364.52

Appraiser remarks

Vehicle inspected at the shop following a side impact at an intersection. The damage to the driver's side is largely consistent with the reported collision, with crumpled rear door panel, cracked rear quarter glass and scuffed sill trim. Repair plan calls for replacing the door shell, reinforcing the pillar, refinishing adjacent panels and recalibrating the side curtain sensor. Labor hours submitted match the scope of the damage. Invoices reviewed show no duplicated line items. No prior damage to this vehicle is on record, so the repairs appear limited to this loss.