Aura - Equipment Not Working Data			
Category	Total No. Of Lights	Borewells	HMWS&SB Meter
S.No	16	21	22
Description of Issue	Lights not working	Borewell not working	HMWSSB meter not working
Root Cause	Due to drivers and lights problem	Pump Shaft damaged	Due to Meter problem
Action Required / Planned	Informed to society for procuring new lights	Quotation submitted to society	Informed to HMWSSB (Token no:6255) & Written letter given to HMWS&SB
Pending from days	226	110	200
Estimated Date of Completion	-	-	-
Responsibility	Society	Society	Society
Notified to the concerned	Society	Society	Society