

MONTHLY MANAGEMENT REPORT

Sarovar

Aparna Property Management Services Pvt. Ltd. February - 2019



This report is a review on our performance during the last month and is an attempt to analyze and evaluate our service delivery and make a progressive step forward with implementation plan.

The following points are put forward for review

Reports:

- Scope and nature of service
- Proposed Manpower and Availability Man power

Technical Services:

- 1. Equipment Status
- 2. Warranty/AMC
- 3. Power Consumption Analysis
- 4. Power Failure Analysis
- 5. DG Generated Power KWH
- 6. WSP Water Test Reports
- 7. STP Water Test Reports
- 8. Fire Safety
- 9. Complaints

Soft Services:

- 1. Horticulture Critical Machinery
- 2. Horticulture Consumables


Others:

- 1. Violations
- 2. Suggestions
- 3. Requisition



REPORTS

❖ Scope and nature of service





❖ Proposed Manpower and Availability Man power

| 0 | Bartindan | | Sh | ift | | | Man power | Manage 20/ |
|------------|--------------------------------------|---------|----|-----|----|-----------------|--------------|------------|
| S.no | Particulars | General | Α | В | С | Manpower (Nos.) | Present days | Man power% |
| Full Time: | • | | | | • | | | |
| 1 | Manager - PMS | 1 | | | | 1 | | |
| 2 | Supervisor - Facilities | 1 | | | | 1 | | |
| 3 | Administrative Support | 2 | | | | 2 | | |
| 4 | Housekeeping Supervisors | 7 | | | | 7 | | |
| 5 | H K Workers | 42 | | | | 42 | | |
| 6 | Security Supervisors and Head Guards | 8 | | | 8 | 16 | | |
| 7 | Security Guards | 25 | | | 25 | 50 | | |
| 8 | Lady Security Guards | | 1 | 1 | | 2 | | |
| 9 | BMS Technicians and Electricians | 2 | | | 1 | 3 | | |
| 10 | Plumbers | 5 | 1 | 2 | 1 | 9 | | |
| 11 | Mechanical Support | 1 | | | | 1 | | |

| 0 | Particulars | Shift | | | | Managara (Nasa) | Man power | Management (|
|-----------|--------------------------|---------|---|---|---|-----------------|--------------|--------------|
| S.no | Particulars | General | Α | В | С | Manpower (Nos.) | Present days | Man power% |
| 12 | Drivers | 1 | | | | 1 | | |
| 13 | Gas Technicians | 1 | | | | 1 | | |
| 14 | Welder | 1 | | | | 1 | | |
| 15 | STP Operators | 2 | 1 | 1 | 1 | 5 | | |
| 16 | Garden Supervisors | 1 | | | | 1 | | |
| 17 | Garden Helpers | 19 | | | | 19 | | |
| 18 | Lift care Takers | 2 | | | | 2 | | |
| 19 | Safety Stewards | 2 | 1 | 1 | 1 | 5 | | |
| 20 | Safety Supervisor | 1 | | | | 1 | | |
| Club Hous | e: | | | • | | | | |
| 21 | Manger - Hospitality | 1 | | | | 1 | | |
| 22 | Reception | | 1 | 1 | | 2 | | |
| 23 | Housekeeping supervisors | 1 | | | | 1 | | |
| 24 | Housekeeping Workers | 3 | 1 | | 1 | 5 | | |
| 25 | Security Head Guards | | 1 | | 1 | 2 | | |

| S.no | Particulars | Shift | | | | Mannawar (Nea) | Man power | Man power% |
|------|------------------------------|---------|---|---|---|-----------------|--------------|---------------|
| | | General | A | В | С | Manpower (Nos.) | Present days | Maii powei /6 |
| 26 | Pool Attendant | 1 | | | | 1 | | |
| 27 | Gym Attendant | | | 1 | | 1 | | |
| 28 | Regular Coaches | 2 | | | | 2 | | |
| 29 | Gym,Swimming Pool Coaches | 4 | | | | 4 | | |

MMR REPORT FOR THE MONTH OF FEBRUARY-2019 APPLIS EXPERIENCE EXCELLENCE



TECHNICAL SERVICES

1. Equipment Status

| | | Sarovar - Equipm | nent Sta | tus as on 2 | 8-2-20 1 | 19 | | |
|--|------|---|----------|-------------|-----------------|-----------|----------|---------------------------------------|
| Category | S.No | Description | Total | Not Working | Pu Auto | mps Statu | s Off | Total Downtime (Hrs). of Equipment |
| | 1 | 3 Panel | 1 | 0 | Auto | Manuai | Oii | Or Equipment |
| EL (1 151 (1 4 | 2 | 4 Panel | 0 | 0 | | | | |
| Electrical Distribution System (HT) | 3 | CTPT | 1 | 0 | | | | |
| | 4 | 5 Panel | 1 | 0 | | | | |
| | 5 | Transformers | 4 | 0 | | | | |
| | 6 | Main Pcc Panel | 8 | 0 | | | | |
| | | APFCR | | | | | | |
| | 8 | Common Supply Panel | 7 | 0 | | | | |
| | | | | | | | | |
| | 9 | Bus Duct | 28 | 0 | | | | |
| Electrical Distribution System(LT) | 10 | Distribution Board | 25 | 0 | | | | 540.1 |
| -y3.0111 <u>(</u> -1) | 11 | VCB | 13 | 1(1) | | | | 542 days |
| | 12 | ACB | 4 | 0 | | | | |
| | 13 | Landscape Lighting Panel | 7 | 0 | | | | |
| | 14 | Club House Panel | 2 | 0 | | | | |
| | 15 | Lighting Arrestor | 7 | 0 | | | | |
| | 16 | Total No. Of Lights | 3393 | 16 (16) | | | | 79 days |
| | 17 | Lifts | 43 | 0 | | | | |
| Elevators & Backup | 18 | DG Sets | 16 | 0 | | | | |
| Power | 19 | ARD Batteries | 43 Sets | - | | | | |
| | 20 | Partial / Full Backup | 100% | - | | | | |
| Ground Water Source | 21 | Borewells | 13 | 9(10) | | | | |
| Metro Water Supply | 22 | HMWS & SB Meter | 1 | 0(1) | | | | |
| | 23 | DWS | Yes | - | | | | |
| Water Distribution | 24 | FWS | Yes | - | | | | |
| System | 25 | PRV's | 784 | 0 | | | | |
| | 26 | Sewerage System | Yes | - | | | | |
| | 27 | Irrigation Pumps | 14 | 2(2) | | | | 171 days |
| Landscape Water | 28 | Irrigation Pump Panels | 7 | 0 | | | | |
| Distribution | 29 | Irrigation Sprinkler Automation System | Auto | - | | | | |
| Water Features | 30 | Water Body Pumps | 5 | 1(1) | | | | 5 days |
| water realures | 31 | Fountain | 1 | 1(1) | | | | 1162 days |
| De-watering System | 32 | Storm Water Pump | 12 | 0 | 12 | 0 | 0 | |
| De-watering System | 33 | Oozing Pumps | 0 | 0 | 0 | 0 | 0 | |
| Dain Water Custom | 34 | Excess Rain Water Pump | 1 | 0 | 1 | 0 | 0 | |
| Rain Water System | 35 | Rain Water Harvesting Pits | 18 | 0 | | | | |
| | 36 | Indoor Pool Pumps | 2 | 0 | | | | |
| Swimming Pool | 37 | Outdoor Pool Pumps | 3 | 0 | | | | |
| | 38 | Baby Pool | Yes | - | | | | |
| | 39 | Boom Barrier | 6 | 3(3) | | | | 552 days |
| Security | 40 | Solar Fencing | 4 | 0 | | | | |
| | 41 | ССТУ | 40 | 0 | | | | |
| Reticulated Piped Gas | 42 | Gas Bank & Chambers | 7 & 4 | - | | | | |



| | | • | Sarovar - Equipme | ent Not Working [| Data | | |
|------------------------------|--|---|--|--|---|---|------------------------------|
| Category | VCB | Total No. Of Lights | Borewells Irrigation Pumps | | Water Body Pumps | Fountain | Boom Barrier |
| S.No | 11 | 16 | 21 | 27 | 30 | 31 | 39 |
| Description of Issue | VCB not working | Lights are not working | Borewells not working | Irrigation pumps not working | L block water body motor not working | Mist Fountain not working | Boom barrier not working |
| Root Cause | VCB breaker pole not functioning due to moisture enter into the breaker | Due to bulbs problem | Due to low ground water and motors burnt | Due to aging | Due to Bearings problem and abnormal sound coming from motor | Due to pipeline damage | Due to communication problem |
| Action Required / Planned | VCB breaker pole to be replaced with new one, informed to Society | Informed to society for procuring of new bulbs | Informed to Society | Informed to society for procuring new pumps | Sent for repair | Informed to society for procuring of new pipe and accessories | Informed to society |
| Pending from days | 542 | 79 | - | 171 | 5 | 1162 | 552 |
| Estimation Date | - | - | - | - | - | - | - |
| Responsibility | Society | Society | Society | Society | APMS | Society | Society |
| Notified to the concerned | Society | Society | Society | Society | APMS | Society | Society |



2. Warranty/AMC

| Asset | Capacity / | Location | Vendor | PO/WO | Warranty | | AN | IC | AMC | Remarks |
|-------------|------------|----------|--------|----------|------------|------------|------------|------------|----------|----------|
| Description | Qty | Location | Name | no. Date | From | То | From | То | (Yes/No) | Remarks |
| Elevator | 10 | sadsa | test | sadsad | 28-03-2019 | 28-03-2019 | 26-03-2019 | 26-03-2019 | sadasasd | sadsadsa |



3. Power Consumption Analysis

| Units | December | January | February |
|--------------------------|----------|---------|----------|
| EB Power Units (KVAH) | 411500 | 401400 | 416696 |
| Solar Power Units (KWH) | 0 | 0 | 0 |
| DG Units Generated (KWH) | 146 | 3702 | 990 |



4. Power Failure Analysis

| Units | December | January | February |
|------------------------|----------|---------|----------|
| Power Failure (Hrs) | 0:46 | 7:6 | 1:34 |
| Diesel Consumed (Ltrs) | 266 | 1376 | 323 |

MMR REPORT FOR THE MONTH OF FEBRUARY-2019 APPLIES



5. DG Generated Power KWH

| S.No | Block | Power Failure (Hrs) | DG Running (Hrs) | DG Units (KWH) | Diesel Consumed (Ltrs) | Diesel filled (Ltrs) |
|------|-------|---------------------|------------------|----------------|------------------------|----------------------|
| 1 | А | 01:34:00 | 2.5 | 102.26 | 50 | 0 |
| 2 | В | 01:34:00 | 1 | 0 | 2 | 0 |
| 3 | С | 01:34:00 | 0.8 | 60 | 7 | 0 |
| 4 | D | 01:34:00 | 2.2 | 30 | 43 | 0 |
| 5 | E | 01:34:00 | 3.8 | 110.56 | 52 | 0 |
| 6 | F | 01:34:00 | 1.9 | 90 | 24 | 0 |
| 7 | G | 01:34:00 | 11.5 | 60 | 16 | 0 |
| 8 | Н | 01:34:00 | 1.7 | 110 | 26 | 0 |
| 9 | I | 01:34:00 | 1.6 | 49.58 | 24 | 0 |
| 10 | J | 01:34:00 | 1.3 | 40 | 22 | 0 |
| 11 | К | 01:34:00 | 2.7 | 120 | 33 | 0 |
| 12 | L | 01:34:00 | 1.2 | 60 | 13 | 0 |
| 13 | М | 01:34:00 | 3 | 120 | 34 | 0 |
| 14 | N | 01:34:00 | 1.6 | 70 | 12 | 0 |



6 (b). WSP-Outlet Water Test Report

TEST REPORT

| Customer Name & Address | | Test Report No. | VCR- | | |
|-------------------------------|--------------------------|--------------------------|------|--|--|
| | | Report Issue Date | | | |
| M/s. Aparna Prope | rty Management Services, | Registration No. | | | |
| H | yderabad. | Registration Date | | | |
| | | Customer Reference | | | |
| Commis Description | WCD Outlet | Reference Date | | | |
| Sample Description | WSP - Outlet | Analysis Starting Date | | | |
| | | Analysis Completion Date | | | |
| Sample Site | Sarovar | Storage Condition | | | |
| | | Condition Upon Receipt | | | |
| Quantity Received | | | | | |
| Sample Collected or Submitted | | | | | |

TEST RESULT

| S.No | Parameters | Units | Test Method | Results | LIMITS |
|---------|--|--------|--------------|---------|---------------|
| Physica | Il & chemical Parameters | • | • | | |
| 1 | рН | - | IS 3025 P-11 | | 6.50-8.50 |
| 2 | Conductivity | ps/cm | APHA | | Not Specified |
| 3 | Colour | Hazen | IS 3025 P-4 | | <5 |
| 4 | Turbiditv | NTU | IS 302s P-10 | | <1 |
| 5 | Total Dissolved Solids | mg / I | IS 3025 P-16 | | <500 |
| 6 | Alkalinity to Phenolphthalein as CaCO ₃ | mg / I | IS 3025 P-23 | | Not Specified |
| 7 | Aikalinity to methyl orange as CaCO ₃ | mg / I | IS 3025 P-23 | | <200 |
| 8 | Total Hardness as CaCO ₃ | mg / I | IS 3025 P-21 | | <200 |
| 9 | Non carbonate I-lardness as CaCO ₃ | mg / I | IS 3025 P-21 | | Not Specified |
| 10 | Calcium as Ca | mg / I | IS 3025 P-40 | | <75 |
| 11 | Maqneslum as Mg | mg / I | IS 3025 P-46 | | <30 |
| 12 | Sodium as Na | mg / I | IS 3025 P-45 | | Not Specified |
| 13 | Pctassiurn as K | mg / I | IS 3025 P-45 | | Not Specified |
| 14 | Iron as Fe | mg / I | IS 3025 P-53 | | <0.3 |
| 15 | Silica as SiO ₂ | mg / I | APHA | | Not Specified |
| 16 | Fluoride as F | mg / I | APHA | | <1.0 |
| 17 | Chlorides as Cl | mg / I | IS 3025 P-32 | | <250 |
| 18 | Sulphates as SO ₄ | mg / I | IS 3025 P-24 | | <200 |
| 19 | Nitrates as NO ₃ | mg / I | IS 3025 P-34 | | <45 |
| 20 | Chlorine demand | mg / I | APHA | | <1.0 |



7(a). Fire Safety

| . (۵): 1 | -ire Safety Fire | e Safety Equip | ment Status | as on 2 | 8-2-2019 | | |
|----------|---|-------------------------|-------------------------|---------|-----------|-----|---------------------------|
| S.No | Description | Saro | var | Fire | Pumps Sta | tus | Total Downtime (Hrs/days) |
| 3.140 | Description | Total | Not Working | Auto | Manual | Off | of all Equipment |
| 1 | Jockey Pump | 14 | 0 | 14 | 0 | 0 | 17:30 Hrs |
| 2 | Main Pump | 14 | 0 | 14 | 0 | 0 | 17:30 Hrs |
| 3 | DG Pump | 14 | 0 | 14 | 0 | 0 | 17:30 Hrs |
| 4 | Booster Pump | 0 | 0 | 0 | 0 | 0 | |
| 5 | Dewatering Pumps | 0 | 0 | 0 | 0 | 0 | |
| 6 | Yard Hydrant Points | 84 | 0 | | | | |
| 7 | Cellar Hydrant Points | 33 | 0 | | | | |
| 8 | Sub Cellar Hydrant Points | 14 | 0 | | | | |
| 9 | Fire Hose Reel Drums | 301 | 0 | | | | |
| 10 | Fire Alarm System | 15 | 0 | | | | |
| 11 | Public Addressing System | 15 | 0 | | | | |
| 12 | Fire Extinguishers | 716 | 0 | | | | |
| 13 | Carbon Emission System | 86 | 0 | | | | |
| 14 | Flow Annunciator Panels - Fire Sprinkler | 14 | 14(14) | | | | |
| 15 | CP Hoses | 677 | 228(228) | | | | |
| 16 | Fire Alarm Repeater Panels | 1 | 1(1) | | | | |
| 17 | Sprinkler Charged (floor wise) | 301 | 18(18) | | | | |
| 18 | Fire Mock Drill & Emergency Evacuation | Prev: 05-01-2019 | Next: 13-07-2019 | | | | |
| 19 | No. of False Alarms | 0 | 0 | | | | |
| 20 | Wet Raisers | 28 | 0 | | | | |
| 21 | Sub Cellar-3 Hydrant Points | 0 | 0 | | | | |
| 22 | Group Indication Panel | 0 | 0 | | | | |

Note:Due to air locks in jockey pumps in N&H blocks, all pumps were kept in off mode for 17:30 hrs. Foot valves were cleaned and reinstalled.

MMR REPORT FOR THE MONTH OF FEBRUARY-2019 APRIL DE LE CELLENCE EXPERIENCE EXCELLENCE



7(b). Fire Safety Not Working

| Sarovar - Equipment Not Working Data | | | | | | | |
|--------------------------------------|---|--|---|--|--|--|--|
| Category | Flow Annunciator Panels - Fire Sprinkler | CP Hoses | Fire Alarm Repeater Panels | Sprinkler Charged (floor wise) | | | |
| S.No | 14 | 15 | 16 | 17 | | | |
| Description of Issue | Flow Annunciator Panel not working | 228 Male & Female CP Hose couplings are missing | Fire Alarm repeater panel not working | Sprinkler system reactivation is pending in 18 floors | | | |
| Root Cause | Due malfunctioning of flow switches | Due Wear & Tear and life span | Due to connectivity and cable problem | Customization of concealed sprinklers is pending 13 floors in different blocks, due to inaccessibility of flats sprinkler reactivation is pending in 05 floors in different blocks | | | |
| Action Required/ Planned | Need to be reactivated the entire system-huge cost involved | Need to be replaced with new CP Hose couplings | Society need to issue the work order | Notices were issued to affected residents by society to modify the sprinkler system at earliest | | | |
| Pending from days | - | - | - | - | | | |
| Estimation Date | - | - | - | - | | | |
| Responsibility | Society | Society | Society | Society | | | |
| Notified to the concerned | Society | Society | Society | Society | | | |

MMR REPORT FOR THE MONTH OF FEBRUARY-2019 AAAN EXPERIENCE EXC



8(c). Status of Fire NOC Renewals as on 03-03-2019

| SAROVAR FIRE NOC DETAILS | | | | | | |
|--------------------------|------------|----------------------|-------------------------|--|--|--|
| S.No | Block | Valid up to | Name Changed to Society | | | |
| 1 | Block - A | 01-02-2021 | Yes | | | |
| 2 | Block - B | 01-10-2022 | Yes | | | |
| 3 | Block - C | 20-11-2020 | Yes | | | |
| 4 | Block - D | 01-03-2021 | Yes | | | |
| 5 | Block - E | 01-03-2020 | Yes | | | |
| 6 | Block - F | 01-03-2020 | Yes | | | |
| 7 | Block - G | 01-03-2020 | Yes | | | |
| 8 | Block - H | 01-03-2019 | Yes | | | |
| 9 | Block - I | 01-10-2022 | Yes | | | |
| 10 | Block - J | 01-10-2022 | Yes | | | |
| 11 | Block - K | 10-01-2024 | Yes | | | |
| 12 | Block - L | 01-10-2022 | Yes | | | |
| 13 | Block - M | 01-03-2020 | Yes | | | |
| 14 | Block - N | 01-03-2020 | Yes | | | |
| 15 | Club House | NOC not yet recevied | Yes | | | |



8 (d). Fire Safety Preparedness & Fire Alarm Operation Training

Sarovar













9. Apna Complex Complaint Report

| Complaint Category | Previous Pending | Opened | Resolved | Total Outstanding | No Escalation | Escalated to L2 | Escalated to L3 |
|--------------------------------|---------------------|--------|----------|----------------------|------------------|-----------------|-----------------|
| Accounts | 19 | 4 | 2 | 21 | 100% | 0 | 0 |
| Carpentery | 2 | 71 | 72 | 1 | 100% | 0 | 0 |
| ссти | 5 | 1 | 1 | 5 | 100% | 0 | 0 |
| Civil | 215 | 8 | 13 | 210 | 100% | 0 | 0 |
| Club House | 16 | 1 | 6 | 11 | 33.33% | 0 | 66.66% |
| Plumbing | 53 | 319 | 313 | 59 | 92.16% | 5% | 2.84% |
| Electrical | 25 | 175 | 173 | 27 | 99.19% | 0.32% | 0.49% |
| Fire & Safety | 13 | 1 | - | 14 | 0 | 0 | 0 |
| Garbage Disposal | 2 | - | - | 2 | 0 | 0 | 0 |
| Reticulatiuon gas | 2 | 29 | 30 | 1 | 97.92% | 0 | 2.08% |
| General | 21 | 3 | 4 | 20 | 100% | 0 | 0 |
| Horticulture | 5 | - | - | 5 | 0 | 0 | 0 |
| Housekeeping | 14 | 1 | 2 | 13 | 100% | 0 | 0 |
| Lifts | 2 | 5 | 3 | 4 | 100% | 0 | 0 |
| Security | 32 | 3 | 3 | 32 | 0 | 0 | 0 |
| No Category | 1 | - | - | 1 | 0 | 0 | 0 |
| Pest Control- community | 1 | - | - | 1 | 0 | 0 | 0 |
| Play Area / Courts | 12 | 2 | 1 | 13 | 0 | 0 | 100% |
| Sritel (Internet, Landline) | 14 | 6 | 2 | 18 | 100% | 0 | 0 |
| Sugguestions | 2 | - | - | 2 | 0 | 0 | 0 |
| telephone | 18 | - | - | 18 | 0 | 0 | 0 |
| UPVC- | 1 | - | - | 1 | 0 | 0 | 0 |
| Utilities Billing | 3 | 1 | 1 | 3 | 100% | 0 | 0 |
| Total | 478 | 630 | 626 | 482 | 96.8% | 0.81% | 2.39% |



SOFT SERVICES

1. Horticulture Critical Machinery

| S.no | Name of Equipment | Qty | Purpose of Use | Availability of Equipment |
|------|-------------------|-----|--------------------|---------------------------|
| 1 | Lawn Mover | 1 | Trimming | 100% |
| 2 | Spayer | 1 | Chemical Spayering | 100% |



2. Horticulture Consumables

| | Horticulture - Pesticides / Fertilizers and Fungicides Consumption Report for | | | | | |
|------|---|------|------|--|--|--|
| S.No | Pesticides / Fertilizers and Fungicides | UOM | Qty | | | |
| 1 | Varmicompost (organic manure) | Kgs | 2600 | | | |
| 2 | Chloropyriphos | Ltrs | 2 | | | |
| 3 | Monocrotophos | Ltrs | 0.2 | | | |
| 4 | Imidaclopride | Ltrs | 1.2 | | | |
| 5 | Carbendazim | Kgs | 0.5 | | | |
| 6 | Dhanvit | Ltrs | 0.35 | | | |
| 7 | Multinutrient Solution | Ltrs | 0.5 | | | |
| 8 | Furadon (G) | Kgs | 10 | | | |
| 9 | Phorate (G) | Kgs | 2 | | | |
| 10 | NPK 19-19-19 | Kgs | - | | | |
| 11 | Acephate(75 SP) | Kgs | - | | | |
| 12 | 17-17-17 | Kgs | 110 | | | |
| 13 | Urea | Kgs | 25 | | | |
| 14 | Potash | - | - | | | |
| 15 | Dimethoate | Ltrs | - | | | |
| 16 | Malathian | Ltrs | - | | | |
| 18 | NPK 15-15-15 | Kgs | - | | | |
| 19 | 2-4 D | Kgs | - | | | |
| 20 | Glycil | Ltrs | - | | | |
| 21 | NPK 16-16-16 | Kgs | - | | | |
| 22 | Thiomethaxion | Ltrs | - | | | |
| 24 | Copper Oxychloride | Kgs | - | | | |
| 25 | NPK 20-20-20 | Kgs | - | | | |
| 26 | Lambda cyhalothrin | Ltrs | 0.2 | | | |



OTHERS

| 1. Violations | | |
|---|--|--|
| Title:Concealed Sprinklers in some of the flats | | |

Description:

Remarks:

Location:



2. Suggestions

| Title:RCBO is use for pt lights | |
|---------------------------------|--|
| Location: | |
| Description: | |
| Remarks: | |

MMR REPORT FOR THE MONTH OF FEBRUARY-2019 APPLES EXPERIENCE EXCELLENCE



| _ | _ | | | | | |
|----|--------------------|--------|----|-----|--------------|---|
| 3. | $\boldsymbol{\nu}$ | \sim | | cti | \mathbf{a} | n |
| J. | 1/6 | 7u | uı | ่อน | v | • |

| Title:Cable needed for pt lights | | |
|----------------------------------|--|--|
| Location: | | |
| Description: | | |
| Remarks: | | |

Sarovar Sarovar



THANK YOU