Fire Safety Equipment Status as on 31-8-2019								
S.No	Description	LakeBreeze		Fire Pumps Status			Total Downtime	
		Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment	
1	Jockey Pump	11	0	11	0	0		
2	Main Pump	11	0	11	0	0		
3	DG Pump	11	0	11	0	0		
4	Booster Pump	NA	-	-	-	-		
5	Dewatering Pumps	8	0	8	0	0		
6	Yard Hydrant Points	NA	-					
7	Cellar Hydrant Points	27	0					
8	Sub Cellar Hydrant Points	20	0					
9	Fire Hose Reel Drums	186	0					
10	Fire Alarm System	12	1					
11	Public Addressing System	12	0					
12	Fire Extinguishers	1314	37					
13	Carbon Emission System	45	0					
14	Flow Annunciator Panels - Fire Sprinkler	NA	-					
15	CP Hoses	516	0					
16	Fire Alarm Repeater Panels	1	0					
17	Sprinkler Charged (floor wise)	NA	-					
18	Fire Mock Drill & Emergency Evacuation	Prev: 25-05-2019	Next: 23-11-2019					
19	No. of False Alarms	NA	0					
20	Wet Raisers	12	0					
21	Sub Cellar-3 Hydrant Points	1	0					
22	Group Indication Panel	1	0					

LakeBreeze - Equipment Not Working Data							
Category	Fire Alarm System	Fire Extinguishers					
S.No	10	12					
Description of Issue	F-Block Fire alarm system not working	Total 37 fire extinguishers were discharged					
Root Cause	Due to PCB board failure	Automatically it was discharged					
Action Required/ Planned	Need to replace new alarm panel	Need to refill					
Pending from days	28 days	30days					
Estimated Date of Completion	05-09-2019	15-09-2019					
Responsibility	Society	Society					
Notified to the concerned	Society	Society					