	Fire Safety Equipment Status as on 31-8-2019							
0.11-	Bassintian	Auı	ra e	Fire	Pumps Stat	us	Total Downtime	
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment	
1	Jockey Pump	1	0	1	0	0		
2	Main Pump	1	0	1	0	0		
3	DG Pump	1	0	1	0	0		
4	Booster Pump	NA	-	-	-	-		
5	Dewatering Pumps	1	0	1	0	0		
6	Yard Hydrant Points	9	0					
7	Cellar Hydrant Points	4	0					
8	Sub Cellar Hydrant Points	4	0					
9	Fire Hose Reel Drums	23	0					
10	Fire Alarm System	1	0					
11	Public Addressing System	1	0					
12	Fire Extinguishers	123	0					
13	Carbon Emission System	30	0					
14	Flow Annunciator Panels - Fire Sprinkler	1	0					
15	CP Hoses	90	0					
16	Fire Alarm Repeater Panels	1	0					
17	Sprinkler Charged (floor wise)	23	0					
18	Fire Mock Drill & Emergency Evacuation	Prev: 24-08-2019	Next : 23-11-2019					
19	No. of False Alarms	NA	0					
20	Wet Raisers	2	0					
21	Sub Cellar-3 Hydrant Points	1	0					
22	Group Indication Panel	1	0					

Fire Safety Equipment Status as on 31-8-2019								
0 N-	D anada dan	Saro	var	Fire	Pumps Stat	us	Total Downtime	
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment	
1	Jockey Pump	14	0	14	0	0	4 hrs	
2	Main Pump	14	0	14	0	0	4 hrs	
3	DG Pump	14	0	14	0	0	4 hrs	
4	Booster Pump	NA	-	-	-	-		
5	Dewatering Pumps	NA	-	-	-	-		
6	Yard Hydrant Points	84	0					
7	Cellar Hydrant Points	33	0					
8	Sub Cellar Hydrant Points	14	0					
9	Fire Hose Reel Drums	301	0					
10	Fire Alarm System	15	0					
11	Public Addressing System	15	0					
12	Fire Extinguishers	716	0(188)					
13	Carbon Emission System	86	0					
14	Flow Annunciator Panels - Fire Sprinkler	14	14(14)					
15	CP Hoses	677	228(228)					
16	Fire Alarm Repeater Panels	1	0				Abandoned	
17	Sprinkler Charged (floor wise)	301	17(17)					
18	Fire Mock Drill & Emergency Evacuation	Prev: 27-07-2019	Next: 25-01-2020					
19	No. of False Alarms	NA	0					
20	Wet Raisers	28	0					
21	Sub Cellar-3 Hydrant Points	NA	-					
22	Group Indication Panel	NA	-					

	Sarovar - Equipment Not Working Data								
Category	Flow Annunciator Panels - Fire Sprinkler	CP Hoses	Sprinkler Charged (floor wise)						
S.No	14	15	17						
Description of Issue	14 no's of Flow Annunciator Panels are not working.	228 Male & Female CP Hose couplings are missing	Sprinkler system reactivation is pending in 17 floors						
Root Cause	Due to malfunctioning of flow switches	Due to wear & tear	Uncovering of concealed sprinklers is pending 12 floors in different blocks, due to inaccessibility of flats sprinkler reactivation is pending in 05 floors in different blocks						
Action Required/ Planned	Need to reactivate the entire system, Involved huge cost	Need to replace with new CP Hose couplings	-						
Pending from days	-	-	-						
Estimated Date of Completion	-	-	-						
Responsibility	Society	Society	Society						
Notified to the concerned	Society	Society	Society						

Fire Safety Equipment Status as on 31-8-2019							
		LakeBı	reeze	Fire Pumps Status			Total Downtime
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment
1	Jockey Pump	11	0	11	0	0	
2	Main Pump	11	0	11	0	0	
3	DG Pump	11	0	11	0	0	
4	Booster Pump	NA	-	-	-	-	
5	Dewatering Pumps	8	0	8	0	0	
6	Yard Hydrant Points	NA	-				
7	Cellar Hydrant Points	27	0				
8	Sub Cellar Hydrant Points	20	0				
9	Fire Hose Reel Drums	186	0				
10	Fire Alarm System	12	1				28 days
11	Public Addressing System	12	0				
12	Fire Extinguishers	1314	37				30 days
13	Carbon Emission System	45	0				
14	Flow Annunciator Panels - Fire Sprinkler	NA	-				
15	CP Hoses	516	0				
16	Fire Alarm Repeater Panels	1	0				
17	Sprinkler Charged (floor wise)	NA	-				
18	Fire Mock Drill & Emergency Evacuation	Prev: 25-05-2019	Next : 23-11-2019				
19	No. of False Alarms	NA	0				
20	Wet Raisers	12	0				
21	Sub Cellar-3 Hydrant Points	1	0				
22	Group Indication Panel	1	0				

LakeBreeze - Equipment Not Working Data									
Category	Fire Alarm System	Fire Extinguishers							
S.No	10	12							
Description of Issue	F-Block Fire alarm system not working	Total 37 fire extinguishers were discharged.							
Root Cause	Due to PCB board failure	Automatically got discharged.							
Action Required/ Planned	Need to replace with new alarm panel	Need to refill							
Pending from days	28	30							
Estimated Date of Completion	30.09.2019	30.09.2019							
Responsibility	Society	Society							
Notified to the concerned	Society	Society							

	Fire Safety Equipment Status as on 31-8-2019							
	2	Cyber	Life	Fire	Pumps Stat	us	Total Downtime	
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment	
1	Jockey Pump	7	0	7	0	0		
2	Main Pump	7	0	7	0	0		
3	DG Pump	4	0	4	0	0		
4	Booster Pump	NA	-	-	-	-		
5	Dewatering Pumps	4	0	4	0	0		
6	Yard Hydrant Points	NA	-					
7	Cellar Hydrant Points	19	0					
8	Sub Cellar Hydrant Points	19	0					
9	Fire Hose Reel Drums	193	0					
10	Fire Alarm System	11	0					
11	Public Addressing System	11	0					
12	Fire Extinguishers	726	0					
13	Carbon Emission System	8	0					
14	Flow Annunciator Panels - Fire Sprinkler	NA	-					
15	CP Hoses	490	0					
16	Fire Alarm Repeater Panels	2	0					
17	Sprinkler Charged (floor wise)	NA	-					
18	Fire Mock Drill & Emergency Evacuation	Prev: 18-05-2019	Next: 15-08-2019					
19	No. of False Alarms	NA	0					
20	Wet Raisers	12	0					
21	Sub Cellar-3 Hydrant Points	1	0					
22	Group Indication Panel	1	0					

	Fire Safety Equipment Status as on 31-8-2019							
0.11	2	Elir	na	Fire Pumps Status			Total Downtime	
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment	
1	Jockey Pump	1	0	1	0	0		
2	Main Pump	2	0	2	0	0		
3	DG Pump	1	0	1	0	0		
4	Booster Pump	2	0	2	0	0		
5	Dewatering Pumps	NA	-	-	-	-		
6	Yard Hydrant Points	14	0					
7	Cellar Hydrant Points	4	0					
8	Sub Cellar Hydrant Points	4	0					
9	Fire Hose Reel Drums	58	0					
10	Fire Alarm System	2	0					
11	Public Addressing System	2	0					
12	Fire Extinguishers	148	0					
13	Carbon Emission System	32	0					
14	Flow Annunciator Panels - Fire Sprinkler	5	0					
15	CP Hoses	5	0					
16	Fire Alarm Repeater Panels	2	0					
17	Sprinkler Charged (floor wise)	1	0					
18	Fire Mock Drill & Emergency Evacuation	Prev: 20-08-2019	Next : 26-02-2020					
19	No. of False Alarms	NA	0					
20	Wet Raisers	2	0					
21	Sub Cellar-3 Hydrant Points	2	0					
22	Group Indication Panel	1	0					

	Fire Safety Equipment Status as on 31-8-2019							
		Kanopy	Tulip	Fire Pumps Status			Total Downtime	
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment	
1	Jockey Pump	NA	-	-	-	-		
2	Main Pump	NA	-	-	-	-		
3	DG Pump	NA	-	-	-	-		
4	Booster Pump	8	0	8	0	0		
5	Dewatering Pumps	NA	-	-	-	-		
6	Yard Hydrant Points	NA	-					
7	Cellar Hydrant Points	NA	-					
8	Sub Cellar Hydrant Points	NA	-					
9	Fire Hose Reel Drums	72	0					
10	Fire Alarm System	NA	-					
11	Public Addressing System	NA	-					
12	Fire Extinguishers	51	0					
13	Carbon Emission System	NA	-					
14	Flow Annunciator Panels - Fire Sprinkler	NA	-					
15	CP Hoses	144	0					
16	Fire Alarm Repeater Panels	NA	-					
17	Sprinkler Charged (floor wise)	NA	-					
18	Fire Mock Drill & Emergency Evacuation	Prev: 23-06-2019	Next: 22-12-2019					
19	No. of False Alarms	NA	0					
20	Wet Raisers	12	0					
21	Sub Cellar-3 Hydrant Points	NA	-					
22	Group Indication Panel	NA	-					

Fire Safety Equipment Status as on 31-8-2019							
0 N	2	Sarovar	Grande	Fire Pumps Status			Total Downtime
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment
1	Jockey Pump	9	0	9	0	0	
2	Main Pump	10	0	10	0	0	
3	DG Pump	9	0	9	0	0	
4	Booster Pump	1	0	1	0	0	
5	Dewatering Pumps	9	0	9	0	0	
6	Yard Hydrant Points	59	0				
7	Cellar Hydrant Points	30	0				
8	Sub Cellar Hydrant Points	30	0				
9	Fire Hose Reel Drums	203	0				
10	Fire Alarm System	10	0				
11	Public Addressing System	10	0				
12	Fire Extinguishers	921	0				
13	Carbon Emission System	125	0				
14	Flow Annunciator Panels - Fire Sprinkler	10	0				
15	CP Hoses	652	0				
16	Fire Alarm Repeater Panels	3	0				
17	Sprinkler Charged (floor wise)	203	0				
18	Fire Mock Drill & Emergency Evacuation	Prev: 16-06-2019	Next : 22-12-2019				
19	No. of False Alarms	NA	0				
20	Wet Raisers	20	0				
21	Sub Cellar-3 Hydrant Points	1	0				
22	Group Indication Panel	1	0				

Fire Safety Equipment Status as on 31-8-2019							
		Towe	ers	Fire Pumps Status			Total Downtime
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment
1	Jockey Pump	1	0	1	0	0	
2	Main Pump	1	0	1	0	0	
3	DG Pump	1	0	1	0	0	
4	Booster Pump	NA	0	0	0	0	
5	Dewatering Pumps	NA	0	0	0	0	
6	Yard Hydrant Points	20	0				
7	Cellar Hydrant Points	11	0				
8	Sub Cellar Hydrant Points	NA	-				
9	Fire Hose Reel Drums	90	0				
10	Fire Alarm System	6	0				
11	Public Addressing System	1	0				
12	Fire Extinguishers	16	0				
13	Carbon Emission System	NA	-				
14	Flow Annunciator Panels - Fire Sprinkler	NA	-				
15	CP Hoses	208	0				
16	Fire Alarm Repeater Panels	NA	-				
17	Sprinkler Charged (floor wise)	NA	-				
18	Fire Mock Drill & Emergency Evacuation	Prev: 16-06-2019	Next: 16-12-2019				
19	No. of False Alarms	NA	0				
20	Wet Raisers	6	0				
21	Sub Cellar-3 Hydrant Points	NA	-				
22	Group Indication Panel	NA	-				

	Fire Safety Equipment Status as on 31-8-2019							
		Wests	side	Fire Pumps Status			Total Downtime	
S.No	Description	Total	Not Working	Auto	Manual	Off	(Hrs/days) of all Equipment	
1	Jockey Pump	1	0	1	0	0		
2	Main Pump	1	0	1	0	0		
3	DG Pump	1	0	1	0	0		
4	Booster Pump	-	-	-	-	-		
5	Dewatering Pumps	1	0	1	0	0		
6	Yard Hydrant Points	4	0					
7	Cellar Hydrant Points	3	0					
8	Sub Cellar Hydrant Points	3	0					
9	Fire Hose Reel Drums	51	0					
10	Fire Alarm System	2	0					
11	Public Addressing System	1	0					
12	Fire Extinguishers	423	0					
13	Carbon Emission System	2	0					
14	Flow Annunciator Panels - Fire Sprinkler	1	0					
15	CP Hoses	128	0					
16	Fire Alarm Repeater Panels	NA	-					
17	Sprinkler Charged (floor wise)	NA	-					
18	Fire Mock Drill & Emergency Evacuation	Prev: 15-08-2019	Next: 30-01-2020					
19	No. of False Alarms	NA	0					
20	Wet Raisers	3	0					
21	Sub Cellar-3 Hydrant Points	NA	-					
22	Group Indication Panel	1	0					