Towers - Equipment Not Working Data		
Category	Lifts	Borewells
S.No	17	21
Description of Issue	A Block service lift not working	Borewell not working
Root Cause	Due to aging	Due to low ground water
Action Required / Planned	Informed to society	Informed to society
Pending from days	30	-
Estimated Date of Completion	New Lift installation work inprogress	-
Responsibility	Society	Society
Notified to the concerned	Society	Society