Kanopy Tulip - Equipment Not Working Data	
Category	Outdoor Pool Pumps
S.No	37
Description of Issue	Outdoor pool pumps not working
Root Cause	Winding problem
Action Required / Planned	Sent for repair
Pending from days	40
Estimated Date of Completion	-
Responsibility	Society
Notified to the concerned	Society