Ba ice

Bhagyanagar Diesels

H.No-5-9-286/2/65, Plot No-65, Near Andhra Jyothi Press, Rajiv Gandhi Nagar,
Moosapet, Kukatpally, I.E., Hyderabad-500072, Cell: 9177111299.
e-mail: bhagyanagardiesels@gmail.com

Authorised Care Centre

KIRLOSKAR **FIELD SERVICE REPORT (F.S.R.)**

Engine Model	App. Code / ESN /		Service Request No.
- 800	DD8 - 1222 1200004		1026
Customer Name, Address & Cont	tact Number	SR open date: 10-	08-8
wis sterna Hill Park Bulewood		Hrs. Run: 534.4	
		Task Start Date & Time: 10 08-19	
- inabana fur		Task End Date & Time: 10 08 - 1-)	
OEM / GOEM	Engine Application:	Alternator / Machine Make / Rating: 320 KUF)	
1 4	1. Genset		
Jaklou 1. Genset 2. Industrial		Alternator / Machine No.: KG 3541.	
- 2	2. Illustrial	Battery Make:	NDV .
		Canopy No.:	AN TOO STATE OF THE STATE OF TH
Failure / Defect Reported / AMC Visit: OMC VISH			
Failure / Defect analysis: Vicited the Site checked the Engine oil			
level found ok, sad above coolant topup level found ox.			
Bettery distilled water level ok 'V-bet Jension			
found ox. all stoknical Cabole Connections are			
tightened, then cleaned the dg Sel			
Action taken: then Start the Engine manually lunning found			
or with out any leakaged.			
Eng. Parameters, 30 minutes of running after		Additional Information:	
rectification		1) Last Service Done: 10-08-19 (534-4)	
1) Full Load R.P.M. 1500 2) Water Temp 0C		2) Grade / Make of Lube Oil: k pil 15 w 45	
3) Lube Oil Temp OC		3) Condition of Air-cleaner:	
4) L.O. Pressure 4.6 box Kg/cm ²		4) Condition of Cylinder liner fins (HA):	
5) Voltage: 415		5) Radiator cleanliness: Normal	
7) Ampere Rhod Y not Ballen		6) Coolant Used: K	- Cool
Major spare parts replaced:			
3)			
2)			
Customer's Remarks:			
Recommendations by Service Representative: Davice to the Custo mer			
Required pil Service, Dix Gilter and Door Egenged			
Right (10) left Side (10)			
The above checks has been carried out by your authorized dealer Rep. M/s. Bhagyanagar Diesels and we are satisfied with the engine performance & understood the maintenance practices to be followed by us in order to keep good health of the engine.			
Name of Service Representative Customer Name			
Name of Service Representative		<i>i</i>	
200 10			
	And the second second	2010	Sec. 11 11 50
Signature	Date	Customer's Signature	10/09/16 Date