CyberZon - Equipment Not Working Data	
Category	Fire Extinguishers
S.No	12
Description of Issue	162 nos. Fire Extinguishers are depressurized & remaining 822 nos. FE to be refilled.
Root Cause	17 nos of CO2,19 nos of H2O,and 08 nos of Dcp fire extinguishers used for fire drills,and pressure was dropped 118 Nos.
Action Required/ Planned	Refilling vendor was finalized & it is in progress.
Pending from days	30
Responsibility	APMS
Notified to the concerned	APMS