Kanopy Tulip STP Not working Data	
Category	Filter Feed Pump
S.No	1
Description of Issue	One of the Filter feed pump is not working
Root Cause	Winding problem
Action Required / Planned	Sent to a workshop for repair
Pending from days	10
Responsibility	APMS
Estimated Date of Completion	30.01.2019
Notified to the concerned	APMS