LakeBreeze - Equipment Not Working Data		
Category	Fire Alarm System	Fire Extinguishers
S.No	10	12
Description of Issue	F-Block Fire alarm system not working	Total 37 fire extinguishers were discharged
Root Cause	Due to PCB board failure	Automatically it was discharged
Action Required/ Planned	Need to replace new alarm panel	Need to refill
Pending from days	28 days	30days
Estimated Date of Completion	05-09-2019	15-09-2019
Responsibility	Society	Society
Notified to the concerned	Society	Society