LakeBreeze - Equipment Not Working Data		
Category	Borewells	ссти
S.No	21	41
Description of Issue	Borewell not working	Cameras not working
Root Cause	Due to low ground water	Due to cable failure
Action Required / Planned	Informed to society	Informed to society
Pending from days	-	15
Estimated Date of Completion	-	05.10.2019
Responsibility	Society	Society
Notified to the concerned	Society	Society