Towers - Equipment Not Working Data		
Category	Lifts	Borewells
S.No	17	21
Description of Issue	A Block service lift not working reason for flat form damaged	Borewell not working
Root Cause	society	Due to low ground water
Action Required / Planned	Given to repair	Informed to society
Pending from days	6 months	-
Estimated Date of Completion	na	-
Responsibility	society	Society
Notified to the concerned	kone to MC	Society