Cyber Life - Equipment Not Working Data		
Category	DG Pump	False Fire Alarms
S.No	3	19
Description of Issue	DG pump kept in OFF mode	On 27.12.2018 at 12:08 Hrs. A block fire alarm activated
Root Cause	LLOP Switch failure	System fault
Action Required/ Planned	To be replace with new one. Informed to local purchase vendor.	Inform to ACEPL & Vendor
Pending from days	18	Rectified immediatly
Estimated Date of Completion	31.01.2019	-
Responsibility	APMS	APMS & ACEPL
Notified to the concerned	APMS	APMS & ACEPL