Sarovar Grande - Equipment Not Working Data			
Category	Total No. Of Lights	Fountain	Outdoor Pool Pumps
S.No	16	31	37
Description of Issue	Lights not working	Pump not working	Pump not working
Root Cause	Due to drivers & LED problem	Due to winding, bearings and impeller damaged	Due to rotor shaft jammed and bearings damaged
Action Required / Planned	Sent for repair	Sent for repair, M/s. Clear water pools replaced one new pump	Sent for repair, M/s. Clear water pools replaced one new pump
Pending from days	15	158	138
Estimated Date of Completion	30.04.2019	10.05.2019	10.05.2019
Responsibility	Society	APMS & M/s. Clear water pools	APMS & M/s. Clear water pools
Notified to the concerned	Society	Society	Society