Sarovar STP Not working Data	
Category	Filter Feed Pump
S.No	1
Description of Issue	Filter feed pumps not working
Root Cause	Bearings problem
Action Required / Planned	IOM sent to purchase department
Pending from days	34
Responsibility	APMS
Notified to the concerned	APMS