Sarovar STP Not working Data			
Category	Raw Sewage Pumps	Air Blowers	De-watering Pump
S.No	2	3	8
Description of Issue	Raw sewage pump not working	Air blower no 2 not working	One of the De-watering pump not working
Root Cause	Motor taking high currents	Due to winding problem	Due to aging
Action Required / Planned	Sent for repair	Sent for repair	Sent for repair
Pending from days	10	15	3
Responsibility	APMS	APMS	APMS
Estimated Date of Completion	07.09.2019	05.09.2019	05.09.2019
Notified to the concerned	APMS	APMS	APMS