## Oosman's Everest Equipment Not working Data

Category		Main Pump	DG Pump	Booster Pumps	Dewatering Pumps	Dointe	Fire Hose Reel Drums	Fire Extinguishers	Flow Annunciator Panels - Fire Sprinkler	CP Hoses	Fire Alaram Repeater Panels	Sprinkler Charged (floor wise)	Fire Mock Drill & Emergency Evacuation	False Fire Alarms	Wet Raisers	Sub Cellar- 3 Hydrant Points	PA System Repeater Panel	Gr Indic Pa
S.No	1	2	3	4	5	7	9	12	14	15	16	17	18	19	20	21	22	
Description of Issue	not working after power failure	12										Sprinkler system in 70 floors need renovation						
Root Cause	not working after power failure	12										Sprinkler system in 70 floors need renovation						
Action Required/ Planned	need proper checking	е																
Pending from days	20	10										10						
Responsibility	responsible of management	0										-						
Notified to the concerned	NA	0										0						