Aura - Equipment Not Working Data	
Category	False Fire Alarms
S.No	19
Description of Issue	Ground floor fire alarm was activated
Root Cause	False zone indication
Action Required/ Planned	Zone-6 Reception area and ground floor checked. No MCP or SD was found activated
Pending from days	Rectified immediately
Estimation Date	-
Responsibility	APMS
Notified to the concerned	APMS