Cyber Life - Equipment Not Working Data	
Category	ссту
S.No	41
Description of Issue	1 no cctv not working in A block passenger lift
Root Cause	Due to communication cable fault
Action Required / Planned	Cable to replaced, informed to vendor
Pending from days	10
Estimated Date of Completion	15.09.2019
Responsibility	M/s. Protocol India Pvt Ltd
Notified to the concerned	M/s. Protocol India Pvt Ltd