Gardenia STP Not working Data	
Category	Filter Feed Pump
S.No	1
Description of Issue	One of the filter feed pumps is not working
Root Cause	Due to bearings problem
Action Required / Planned	Sent to workshop for repair
Pending from days	15
Responsibility	APMS
Estimated Date of Completion	04.05.2019
Notified to the concerned	APMS