Cyber Life STP Not working Data	
Category	Chlorine Dosing Pump
S.No	10
Description of Issue	Chlorine dosing pump not working
Root Cause	Diaphragm failed
Action Required / Planned	sent for servicing
Pending from days	3
Responsibility	M/s. Revolve Engineers
Estimated Date of Completion	25.07.2019
Notified to the concerned	APMS