



Polysom Prototype schematic (July 2026)

Linear charger
500mA
USB →




5V
GND
3V3(OUT)

UART	PWM	I2S	ADC	I2C	GP0
UART	PWM	I2S	ADC	I2C	GP1
UART	PWM	I2S	ADC	I2C	GP2
UART	PWM	I2S	ADC	I2C	GP3
CS(SD)				I2C	GP4
MISO(SD)				I2C	GP5




TX
RX
GP13
GP12
GP23
GP20
GP19
GP18
GP9

BTN1



UART0 TX
UART0 RX

(SDA)
(SCL)
(SD)



BTN2

SDP800 LCL1612 DS1307 MMA8451

