



m Crystallization / 12

Fines MAE 0-0.52




n Crystallization / 24

Fines MAE 0-0.52



o Purification / purity

Purity MAE 0-0.42



p Purification / recovery

Recovery MAE 0-0.14

