

N = number of samples on the rotation disc (table) n = number of measurements per sample



- 1. Go to menue Option
- 2. Choose Rotatoin-DC-Setup







