8304239





3		SPIKE		
4		NUT-3/4-10-LOCK		
10		NUT-3/4-10-LOCK		12
4		BOLT-3/4-10 HEX. HD.		11
4		BOLT-3/4-10 [illegible]		
6		BOLT-3/4-10-HEX. HD.		
2		[illegible]		
2		[illegible]		
1		[illegible]		
1		[illegible]		
2		[illegible]		
1		MIND. [illegible]		
1		HANDRAIL ASSEMBLY		
1		HANDRAIL ASSEMBLY		

MATERIAL — NAME OF PART — PART NO.

REV. LTR.	REVISION	DATE	BY	CK.	APV'D.
A-60	D	IT'S. 1 & 2 REV'D. PER DET.	5-8-63		
Y-0849	C	IT. 12 WAS 6 REQ'D.			
		IT. 11 REINSTATED, QTY. WAS 8.	4-3-62		
	B_6	SECTION B-B REMOVED.			
	B_5	WELD SYMBOL REMOVED.			
CONT.	B_4	DRILL NOTE REMOVED.			
X-3936	B	B_2 1/8 DIM. REM'D. B_1 1/8 DIM. REM'D.			
		REM'D NOTE-ADDED (2 PLCS.)			
		IT'S. 3, 4, 5, 7, 8, 10, 11, 13, 14 REM'D.			
		IT. 12 WAS "14 REQ'D."			
		IT. 2 WAS "HANDRAIL-[illegible]"			
		IT. 1 WAS "HANDRAIL-[illegible]"			
Y-1164	A	IT. 7 REV'D. PER DETAIL.			
		IT. 6 REM'D. - IT. 7 WAS 6 REQ'D.			

FIRST USED ON: GP-36

DRAWN BY: [illegible] 1-3-61
CHECKED BY: [illegible] 2-4-61
ENGR. CHG.: [illegible]
DATE OF ISSUE: [illegible]

ELECTRO MOTIVE DIVISION
GENERAL MOTORS CORPORATION
LA GRANGE, ILLINOIS, U.S.A.

HANDRAIL ASSEMBLY

8304239