







⑦	AUG 15/83		NEXT REVISION	DIODES REPLACED BY SURGE DEVICE ON PRESENT TYPE TRANSFORMER, PER TS 84-A
⑥	MAR 3/82		NEXT REVISION	⑤ TO ⑥ CHANGED TO REFLECT PRESENT TYPE
⑤	OCT 29/81		NEXT REVISION	DIV. LANDO TRAV SUSPENDED CIRCUITS
④	AUG 4/81		NEXT REVISION	WIRING ERRORS, NO SUPPLY CHANGES
③			NEXT REVISION	DS-6, DS-9 (S.T.O.S.) ADDED
			300 V.D.C.	
SYM	DATE	BY	FILE	APPLICATION	AUTHORIZATION
REVISED					

MECHANICAL DEPARTMENT

CP Rail

WINDSOR STATION, MONTREAL, QUE.

ELECTRICAL TERMINAL BOARDS

S-65-DE-178-D