
## Xphase 相字

# Xphase JPG to PNO conversion tool User manual



©Beijing Xiang Feng Ming Tian Technology Co., Ltd., 2019.1

## Software introduction

Xphase The JPG to PNO conversion tool was independently developed by Beijing Xiang Feng Ming Tian Technology Co., Ltd., which is used to batch convert post-processed ".jpg" files into panoramic photo files (" .pno " files) for easy browsing and roaming production.

### Software installation

- 1 Equipment requirements
- 1.1 The computer's memory is no less than 4GB, 64-bit operating system, the operating system version is not lower than Windows7
- 2 Software acquisition and installation
- 2.1 This program will also be installed when installing "Xphase Panorama Manager ". Please refer to the Xphase Panorama Manager User Manual

### **Instructions**

#### 1 Precondition

1.1 The Xphase Panorama Manager is used to "Advanced Pattern Stitching" on the selected panoramic raw data file to generate a 16-bit lossless compressed PNG format panorama and an ".inf" file for recording related information. For detailed steps, please refer to the Xphase Panorama Manager User Manual

1.2 Use the tools such as Photoshop to post-process the PNG format

panorama and save it as ".jpg" format, placed in the same folder as the

corresponding ".inf" file

2 Select the ".jpg" file to convert

2.1 Start Xphase JPG to PNO conversion tool, click the "Select File" button at

the bottom of the interface to select the ".jpg" file to be converted

Can select multiple files

Ensure that the corresponding ".inf" file in the same folder

3 Batch convert ".jpg" files

3.1 Click the "Start Processing" button at the bottom of the interface, the

software will convert the ".jpg" file in the list into a panoramic photo file

(".pno" file) in turn, and save it in the same path as the corresponding ".jpg"

The conversion progress will be displayed on the right side of the list

Beijing Xiang Feng Ming Tian Technology Co., Ltd.

Email: bd@xphase.cn

Tel: +86-10-80748211