
Xphase 相字

Xphase PNO to JPG conversion tool User manual



©Beijing Xiang Feng Ming Tian Technology Co., Ltd., 2019.1

Software introduction

Xphase PNO to JPG conversion tool was independently developed by Beijing

Xiangfeng Tomorrow Technology Co., Ltd., used to batch convert panoramic photo

files (".pno" files) into ".jpg" files.

Software Installation

1 Equipment requirements

1.1 The computer's memory is not less than 4GB, 64-bit operating system, the operating system version is not lower than Windows7

2 Software acquisition and installation

2.1 This program will be installed when installing "Xphase Panorama Manager" .

Please refer to "Xphase Panorama Manager User Manual" .

Instructions for use

1 Select the ".pno" file to be converted

1.1 Start the Xphase PNO to JPG conversion tool, click the "Select File" button at the bottom of the interface, and select the ".pno" file to be converted.

Can select multiple files

2 Convert ".pno" files in batches

2.1 Click the "Start Processing" button at the bottom of the interface, the software will convert the panoramic photo file (".pno" file) in the list into ".jpg" file in turn, and save it in the same path as the corresponding ".pno".

The conversion progress will be displayed on the right side of the list.

Beijing Xiang Feng Ming Tian Technology Co., Ltd.

Email: bd@xphase.cn

Tel: +86-10-80748211