DOA Replacement Request — Critical Hardware Failure

Date: February 19, 2026 **Customer:** Suraj Satyarthi **Device:** MacBook Air (M2/M3) **Purchase Date:** Feb 1, 2026 | **Delivered:** Feb 8, 2026 **Status: Day 11 of Ownership** (Inside DOA Window)

---

1. The Request

I am requesting a Dead-On-Arrival (DOA) Replacement Unit.

This is a brand-new device (11 days old) exhibiting a confirmed Logic Board / GPU / Power Subsystem hardware failure. **I do not accept a repair** for a product that exhibited hardware defects from Day 1 of use.

Apple Support Case IDs:

- `102824938226` — Escalated to Senior Advisor (call completed 11:00 AM, Feb 19, 2026)
- `102824929878`

> ***Note:*** *This service center appointment was* ***booked directly by the Apple Senior Advisor*** *following a recorded phone call on Feb 19, 2026 at 11:00 AM. The advisor reviewed the system logs, confirmed the hardware defect, and instructed the customer to obtain a Job Card for DOA replacement processing. The call is on record.*

What I Need from the Service Center:

- A **Job Card / Service Report** confirming the hardware defect.
- Please explicitly note **"WindowServer Watchdog Timeout"**, **"AGXHardwareWorkLoop hang"**, **"AppleCLPC failure"**, and **"Display Brightness: nan"** in the report.
- This report will be used to finalise the DOA replacement authorisation with the Apple Senior Advisor.

---

2. Crash History — Live System Evidence (3 Hardware Crashes Since Day 1)

The following is extracted directly from the system's live session log (`last reboot`), which is **independent of any saved file** and cannot be manually altered.

A `reboot` entry **without** a preceding `shutdown` entry = **forced crash reboot** (hardware failure).

Date	Event	Classification
Feb 8, 10:36 AM	First boot (delivery day)	Start of ownership
Feb 9, 1:43 PM	Reboot — NO preceding shutdown	**HARDWARE CRASH #1 — Day 1 of use**

Feb 12	Normal restart	OK
Feb 18, 7:26 PM	Reboot — NO preceding shutdown	**HARDWARE CRASH #2**
Feb 19, 4:50 AM	Forced shutdown → reboot at 4:53 AM	**HARDWARE CRASH #3 — Documented WATCHDOG crash**

This machine has suffered 3 confirmed hardware crash reboots, the first occurring on Day 1 of use (Feb 9).

---

3. Root Cause Analysis — Hardware Failure Chain

The crash at **Feb 19, 04:49:34 AM** (Incident ID: `065518E0-E4BD-4396-B615-E33164D18104`) has been fully analysed from the `.ips` crash report. The failure is a **cascading hardware deadlock** originating in the power management subsystem.

Failure Chain (in order of occurrence)

`

[Step 1] AppleCLPC (CPU/Power Management Controller)

→ Hung for 484 seconds (~8 minutes BEFORE the visible crash)

→ State: TH_WAIT / TH_UNINT (uninterruptible — waiting on hardware)

[Step 2] AGXHardwareWorkLoop (Apple GPU Hardware Driver)

→ Hung for 134.47 seconds

→ State: TH_WAIT / TH_UNINT

→ GPU hardware stopped responding to driver commands entirely

[Step 3] IOGPU Completion (GPU I/O Interface)

→ Hung for 82.02 seconds

→ State: TH_WAIT / TH_UNINT

→ GPU I/O pipeline completely frozen

[Step 4] VM_pageout_scan + VM_compressor (Memory Management)

→ Both hung for ~80 seconds

→ Memory operations stalled due to GPU memory lockup

[Step 5] WindowServer failed to check in for 40 seconds

→ macOS WATCHDOG timer triggered

→ Termination Reason: WATCHDOG, monitoring timed out for service

→ Forced reboot

`

Key Thread Data (from crash log)

Thread	Role	Hang Duration	State
`AppleCLPC`	CPU/Power Management Controller	**484 seconds**	TH_WAIT / TH_UNINT
`AGXHardwareWorkLoop`	Apple GPU hardware driver	**134.47 seconds**	TH_WAIT / TH_UNINT
`IOGPU Completion`	GPU I/O interface	**82.02 seconds**	TH_WAIT / TH_UNINT
`VM_pageout_scan`	Virtual memory manager	**82.00 seconds**	TH_WAIT / TH_UNINT
`VM_compressor`	Memory compression	**78.80 seconds**	TH_WAIT / TH_UNINT

Why This Is a Hardware Defect (Not Software)

- `TH_UNINT` (uninterruptible wait) means threads are **waiting on hardware signals that never arrive** — this cannot be caused or fixed by software
- `AppleCLPC` is a **kernel-level hardware power controller** — no user application or macOS update can corrupt it
- The failure pattern has **repeated 3 times since Day 1**, ruling out any one-time software glitch
- This confirms a **manufacturing defect** in the Logic Board's power delivery or GPU subsystem

---

4. Technical Evidence Summary

A. Crash Report (Apple-generated, system log)

- **File:** `WindowServer-2026-02-19-044934.ips` (saved on Desktop, also in `~/Library/Logs/DiagnosticReports/`)
- **Termination Reason:** `WATCHDOG, monitoring timed out for service`
- **Key Evidence:**

- `AGXHardwareWorkLoop`: System Time **134.47s**, State: `TH_WAIT TH_UNINT`

- `AppleCLPC`: System Time **484.52s**, State: `TH_WAIT TH_UNINT`

B. Display Corruption (Syslog)

- `WindowServer[396]: (QuartzCore) Display 1 swap brightness: nan, limit: nan, indicator brightness: nan`
- Confirms the display controller pipeline is receiving corrupt/invalid data from the GPU

C. Live Reboot History (Terminal: `last reboot`)

- 3 crash reboots confirmed since Feb 8 (delivery date)
- First crash on Feb 9 = **Day 1 of use**

D. Apple Support Cases (Transcripts attached)

- Case `102824929878` — Initial report, Feb 19 at 6:07 AM
- Case `102824938226` — Escalated to Senior Advisor, Feb 19 at 6:27 AM; phone call at 11:00 AM

---

5. Instructions for the Technician

Step 1: Verify Crash Log in Console.app

1. Open **Console.app**
2. Go to **Crash Reports** → locate `WindowServer-2026-02-19-044934.ips`
3. Search (`Cmd+F`) for:

- `WATCHDOG` → confirms forced termination by OS watchdog
- `AGXHardwareWorkLoop` → confirms GPU driver hang (134 seconds)
- `AppleCLPC` → confirms power controller hang (484 seconds)

Step 2: Verify Reboot History in Terminal

`

last reboot

`

Look for `reboot` entries with **no preceding** `**shutdown**` — each one is a crash reboot.

Step 3: Run MRI / AST2 Diagnostics

Please run Apple's internal hardware diagnostics (MRI / AST2) to confirm Logic Board / GPU subsystem failure and document findings on the Job Card.

---

6. Conclusion

This unit has a **confirmed manufacturing defect** in the Logic Board's power management and GPU subsystem, evidenced by:

1. 3 crash reboots since Day 1 of use (live system log)
2. AppleCLPC power controller hung for 484 seconds (kernel thread)
3. AGXHardwareWorkLoop GPU driver hung for 134 seconds (hardware unresponsive)
4. Display controller sending corrupt `nan` brightness values

I request the technician to document these specific failures on the Job Card so the Apple Senior Advisor (Case 102824938226) can process the DOA replacement authorisation.

A repair (logic board replacement) is **not acceptable** for a brand-new unit that has failed from Day 1.

Customer Contact: Suraj Satyarthi | 8839912611 Apple Support Case (Senior Advisor): 102824938226