

AI Automotive Diagnostic Report

Vehicle Information

Make	Toyota
Model	corolla
Year	2018
Mileage	52000
Fuel Type	Petrol
Transmission	Automatic
Engine	N/A
Symptom Category	Engine
OBD-II Code	None

Customer Symptoms

car idle is not satable

AI Diagnosis

Vehicle Summary

- The vehicle is a 2018 Toyota Corolla with 52,000 miles, petrol engine, and automatic transmission. The customer reports an unstable idle.

Likely Cause

- The most likely cause of the unstable idle is a faulty or clogged Idle Air Control (IAC) valve, or a malfunctioning throttle position sensor. However, without further information or specific diagnostic codes, it's challenging to pinpoint the exact cause.

Possible Causes

- Other possible causes of the unstable idle include:
 - * Faulty spark plugs or spark plug wires
 - * Clogged fuel injectors or fuel filter
 - * Vacuum leaks or intake manifold issues
 - * Mass Airflow Sensor (MAF) malfunction
 - * Crankshaft Position Sensor (CKP) or Camshaft Position Sensor (CMP) issues
 - * Ignition coil problems
 - * PCV system blockages or issues

Diagnostic Steps

- To diagnose the issue, the following steps should be taken:
 - * Perform a visual inspection of the engine and its components to look for any signs of damage,

wear, or leaks

- * Use a scan tool to monitor engine parameters, such as idle speed, throttle position, and fuel trim
- * Check the spark plugs, spark plug wires, and ignition coil for any signs of wear or damage
- * Inspect the fuel injectors, fuel filter, and fuel pressure regulator for any blockages or issues
- * Use a vacuum gauge to check for any vacuum leaks or intake manifold issues
- * Perform a throttle body cleaning and inspection
- * Check the PCV system for any blockages or issues

Recommended Repair

- Based on the likely cause, the recommended repair would be to replace the Idle Air Control (IAC) valve or throttle position sensor, if faulty. Additionally, spark plugs, spark plug wires, and ignition coil should be inspected and replaced if necessary.

Required Parts

- The required parts may include:

- * Idle Air Control (IAC) valve
- * Throttle position sensor
- * Spark plugs
- * Spark plug wires
- * Ignition coil
- * Fuel injectors (if clogged)
- * Fuel filter
- * Vacuum hoses or intake manifold gasket (if damaged)

Estimated Labour

- The estimated labour time for the repair would be around 2-5 hours, depending on the complexity of the issue and the specific repairs required.

Safety Warning

- The vehicle may not be safe to drive if the unstable idle causes the engine to stall or hesitate, especially in traffic or when driving at high speeds. It's recommended to have the issue addressed as soon as possible to avoid any potential safety risks.

Maintenance Advice

- Regular maintenance, such as spark plug replacement, transmission fluid changes, coolant checks, and brake fluid inspections, can help prevent issues like unstable idle. It's also essential to address any issues promptly to avoid more severe problems down the road.

Confidence Score

- Based on the provided information, my confidence score is 60%. More information, such as specific diagnostic codes or further inspection results, would be necessary to increase the confidence score and provide a more accurate diagnosis.

Note: The model name "corplla" seems to be a typo, and it's likely that the correct model name is "Corolla". Additionally, the engine size is unknown, which could be helpful in providing a more accurate diagnosis.

Diagnostic Tools

Diagnosis	No specific diagnosis found for 2018 Toyota corplla. A complete inspection is recom
Repair Cost	Estimated cost: R4,500 - R18,000

Maintenance	Recommended: - Spark plugs - Transmission fluid - Coolant - Brake fluid
OBD-II	No OBD-II code supplied.

AI Confidence Score

95%

Generated on: 2026-07-03 09:35:55.326883

Powered by Groq + LangChain + Gemini Vision