

AI Automotive Diagnostic Report

Vehicle Information

Make	toyota
Model	tazz
Year	2005
Mileage	146000
Fuel Type	Petrol
Transmission	Automatic
Engine	N/A
Symptom Category	Engine
OBD-II Code	None

Customer Symptoms

enging is shaking on idle

AI Diagnosis

Vehicle Summary

- The vehicle is a 2005 Toyota Tazz with 146,000 miles, petrol engine, and automatic transmission. The engine size is unknown. The customer reports that the engine is shaking on idle.

Likely Cause

- The most likely cause of the engine shaking on idle is a faulty or clogged fuel injector, spark plug issue, or a vacuum leak. However, without further diagnosis, it's difficult to pinpoint the exact cause.

Possible Causes

- Additional possible causes include:
 - * Faulty ignition coil
 - * Clogged air filter
 - * Faulty oxygen sensor
 - * Low compression in one or more cylinders
 - * Worn or loose engine mounts
 - * Faulty idle air control valve

Diagnostic Steps

- To diagnose the issue, the following steps should be performed:
 - * Visual inspection of the engine and its components
 - * Check the spark plugs and replace them if necessary
 - * Use a scan tool to monitor engine performance and check for any trouble codes (even though

none were reported)

- * Perform a fuel injector cleaning or replacement if necessary
- * Check the vacuum system for any leaks or blockages
- * Use a compression test to check for low compression in any cylinders
- * Inspect the engine mounts and replace them if necessary

Recommended Repair

- The recommended repair will depend on the results of the diagnostic tests. If a faulty fuel injector or spark plug is found, replacement will be necessary. If a vacuum leak is detected, the leak will need to be repaired. If the engine mounts are worn or loose, they will need to be replaced.

Required Parts

- The required parts will depend on the diagnosis, but possible parts include:

- * Spark plugs
- * Fuel injectors
- * Oxygen sensor
- * Air filter
- * Ignition coil
- * Engine mounts
- * Idle air control valve

Estimated Labour

- The estimated labour time will depend on the complexity of the repair, but it could range from 2-10 hours.

Safety Warning

- The vehicle may not be safe to drive if the engine shaking on idle is causing a loss of power or control. It's recommended to have the vehicle towed to a repair shop if the shaking is severe.

Maintenance Advice

- As a high-mileage vehicle, regular maintenance is crucial to prevent further issues. It's recommended to:

- * Check and replace the spark plugs every 30,000-100,000 miles
- * Check and replace the air filter every 15,000-30,000 miles
- * Check the fuel injector condition and clean or replace them as necessary
- * Check the engine oil and top it off as necessary

Confidence Score

- Based on the information provided, my confidence score is 60%. Further diagnosis and testing are needed to determine the root cause of the issue and provide a more accurate diagnosis and repair plan. Additional information about the vehicle's service history, accident history, and engine size would be helpful in providing a more accurate diagnosis.

Diagnostic Tools

Diagnosis	No specific diagnosis found for 2005 toyota taz. A complete inspection is recommended.
Repair Cost	Estimated cost: R4,500 - R18,000
Maintenance	High mileage vehicle. Complete inspection recommended.
OBD-II	No OBD-II code supplied.

AI Confidence Score

95%

Generated on: 2026-07-06 10:35:46.851607

Powered by Groq + LangChain + Gemini Vision