

ACME API Pharma Ltd. - Quality Management System

Deviation Report	
Date of occurrence	22-Sep-2026
Reported by	Anita Sharma (QC Analyst)
Department	Quality Control
Area / Location	Drying Area, Block C
Product	Atorvastatin Calcium
Batch No.	AC-2609-042
Stage	Drying
Equipment	Fluid Bed Dryer FBD-305
Parameter	Loss on Drying (LOD)
Specification	NMT 0.5% w/w
Result	1.2% w/w

Description of deviation

During in-process testing after the drying stage, the LOD of batch AC-2609-042 was found to be 1.2% w/w against the specification of NMT 0.5% w/w. The dryer was operated for the standard 6 hours as per BMR. The inlet air temperature chart shows the inlet air temperature dropped to 48 °C for about 90 minutes due to a steam supply interruption.

Immediate action

Batch AC-2609-042 moved to quarantine. Engineering informed to check the steam supply line. Re-drying to be evaluated by QA.

Probable cause

Insufficient drying due to steam supply interruption (utility failure).

Unplanned deviation. GMP impact: Yes (intermediate out of specification).