Ashford Auto Glass

92 Station Rd, Ashford, VA 23991 | (804) 555-0163

GLASS REPLACEMENT QUOTE
No. AAG-Q-26-1027-14
Date: 2026-10-27

Customer	Priya Raman
Vehicle / Property	2021 Honda CR-V EX | VIN 7FARW2H83ME014472 | Plate VA UKP-2207

#	Description	Qty	Unit	Unit price	Amount
1	Windshield, OEM-equivalent, w/ rain sensor & camera bracket	1	ea	$365.00	$365.00
2	Urethane & molding kit	1	ea	$32.00	$32.00
3	Labor - remove & install windshield	1.5	hr	$58.00	$87.00
4	ADAS forward camera static recalibration	1	ea	$215.00	$215.00
5	Shop supplies / glass disposal	1	ea	$18.00	$18.00
	TOTAL				**$717.00**

Notes / Findings

Crack approx. 14 in., passenger side, extending from impact point near lower edge. Replacement required (crack exceeds repairable length). Camera recalibration required by manufacturer after windshield replacement.

Prices valid 30 days. Hidden damage may require a supplement. Payment is the responsibility of the customer unless the insurer has authorized direct payment in writing.