Riverton Auto Body

455 Canal St, Riverton, VA 23992 | (804) 555-0162

REPAIR ESTIMATE
No. RAB-26-1187
Date: 2026-10-23

Customer	Elena Sokolova
Vehicle / Property	2022 Subaru Outback Premium | VIN 4S4BTACC2N3157726 | 29,800 mi

#	Description	Qty	Unit	Unit price	Amount
1	Front bumper cover	1	ea	$472.00	$472.00
2	Front bumper reinforcement	1	ea	$312.00	$312.00
3	Headlamp assembly, left (LED)	1	ea	$985.00	$985.00
4	Front fender, left	1	ea	$344.00	$344.00
5	Fender liner, left	1	ea	$78.00	$78.00
6	Hood panel	1	ea	$598.00	$598.00
7	Grille assembly	1	ea	$286.00	$286.00
8	Body labor	14.6	hr	$60.00	$876.00
9	Frame labor - measure & pull front left rail	3.5	hr	$74.00	$259.00
10	Refinish labor	9.8	hr	$60.00	$588.00
11	Paint & materials	9.8	hr	$40.00	$392.00
12	Wheel alignment (sublet)	1	ea	$129.00	$129.00
13	ADAS radar/camera calibration (sublet)	1	ea	$240.00	$240.00
14	Hazardous waste	1	ea	$30.00	$30.00
	TOTAL				**$5,589.00**

Notes / Findings

Front left impact. Possible hidden damage behind reinforcement; supplement may follow after teardown.

Prices valid 30 days. Hidden damage may require a supplement. Payment is the responsibility of the customer unless the insurer has authorized direct payment in writing.