Millbrook Collision Center

1880 Industrial Blvd, Millbrook, VA 23990 | (804) 555-0161

REPAIR ESTIMATE
No. RO-26-4398
Date: 2026-10-19

Customer	David Okafor
Vehicle / Property	2020 Toyota Highlander XLE | VIN 5TDGZRBH8LS052291 | 52,300 mi

#	Description	Qty	Unit	Unit price	Amount
1	Front door shell, left	1	ea	$892.00	$892.00
2	Rear door shell, left	1	ea	$846.00	$846.00
3	Front door glass, left	1	ea	$296.00	$296.00
4	Rear door glass, left	1	ea	$242.00	$242.00
5	Side mirror assembly, left (heated, signal)	1	ea	$438.00	$438.00
6	Side curtain airbag, left (deployed)	1	ea	$1,180.00	$1,180.00
7	Seat belt pretensioner, driver	1	ea	$362.00	$362.00
8	Alloy wheel, front left (bent)	1	ea	$398.00	$398.00
9	Tire, front left	1	ea	$212.00	$212.00
10	Lower control arm, front left	1	ea	$286.00	$286.00
11	Frame labor - B-pillar reinforcement repair	4	hr	$74.00	$296.00
12	Body labor	16.2	hr	$58.00	$939.60
13	Refinish labor	10.5	hr	$58.00	$609.00
14	Paint & materials	10.5	hr	$39.00	$409.50
15	Mechanical labor - trim transfer, airbag module, SRS	2.5	hr	$112.00	$280.00
16	Mechanical labor - suspension R&R	2.2	hr	$112.00	$246.40
17	Pre/post repair diagnostic scan (sublet)	1	ea	$145.00	$145.00
18	Wheel alignment (sublet)	1	ea	$129.00	$129.00
19	Towing (sublet)	1	ea	$185.00	$185.00
20	Storage	3	day	$55.00	$165.00
21	Hazardous waste	1	ea	$30.00	$30.00
	TOTAL				**$8,586.50**

Notes / Findings

Driver side impact at B-pillar. Left curtain airbag deployed. Vehicle not drivable.

Prices valid 30 days. Hidden damage may require a supplement. Payment is the responsibility of the customer unless the insurer has authorized direct payment in writing.