Brookhaven Body Works

77 Mill Race Rd, Brookhaven, VA 23993 | (804) 555-0165

REPAIR ESTIMATE
No. BBW-26-0912
Date: 2026-10-12

Customer	Robert Chen
Vehicle / Property	2014 Honda Civic LX | VIN 19XFB2F58EE063118 | 128,900 mi

#	Description	Qty	Unit	Unit price	Amount
1	Front bumper cover	1	ea	$405.00	$405.00
2	Front bumper reinforcement	1	ea	$268.00	$268.00
3	Headlamp assembly, left (halogen)	1	ea	$296.00	$296.00
4	Headlamp assembly, right (halogen)	1	ea	$296.00	$296.00
5	Hood panel	1	ea	$512.00	$512.00
6	Front fender, left	1	ea	$268.00	$268.00
7	Front fender, right	1	ea	$268.00	$268.00
8	Grille assembly	1	ea	$196.00	$196.00
9	Radiator support	1	ea	$486.00	$486.00
10	Radiator	1	ea	$342.00	$342.00
11	A/C condenser	1	ea	$388.00	$388.00
12	Driver front airbag	1	ea	$812.00	$812.00
13	Passenger front airbag	1	ea	$924.00	$924.00
14	Seat belt pretensioners (2)	2	ea	$336.00	$672.00
15	Airbag control module	1	ea	$465.00	$465.00
16	Windshield (cracked by airbag)	1	ea	$345.00	$345.00
17	Body labor	22.5	hr	$58.00	$1,305.00
18	Frame labor	8	hr	$74.00	$592.00
19	Refinish labor	12	hr	$58.00	$696.00
20	Paint & materials	12	hr	$39.00	$468.00
21	Mechanical labor - A/C evacuate & recharge, cooling system	6.5	hr	$112.00	$728.00
22	Towing (sublet)	1	ea	$210.00	$210.00
23	Storage	6	day	$55.00	$330.00
	TOTAL				**$11,272.00**

Notes / Findings

Heavy frontal impact. Both front airbags deployed. Repair cost likely exceeds vehicle value - recommend total loss evaluation.

Prices valid 30 days. Hidden damage may require a supplement. Payment is the responsibility of the customer unless the insurer has authorized direct payment in writing.