SURVEY OF INDIA भारतीय सर्वेक्षण विभाग

दूरभाष: 135-2713296

Tel. No: 135-2713296

ई.मेल. sgw.grb.soi@gov.in

E-mail- sgw.grb.soi@gov.in



उपग्रहज्योडीयविंग Satellite Geodesy Wing ज्योडीयएवंअनुसन्धानशाखा GEODETIC & RESEARCH BRANCH 17-ईo सी॰रोड, देहरादून (उत्तराखंड) 17-E.C. Road, Dehradun (U.K.)

Letter No. | 44 / 39-C-CORS.

Dated: 09 -11-2022

To,

The Director

Geodetic and Research Branch,

17 E.C. Road, Dehradun

Sub: Penalty for Non-Rectification of CORS in U.P., UK, H.P., M.P. and Haryana – reg.

Sir,

Your kind attention is invited to para (b) of **GCC 28.5** of the CORS Contract agreement between M/s Trimble Mobility Solutions India Pvt. Ltd and Survey of India, which states that the period for repair or replacement shall be:

"For receiver station 7 working days from time of reporting. If repair and replacement not be completed within 7 working days, penalty of Rs. 5000/- per day per station shall be charged over period in which receiver station remains un-operational."

The following CORS were not rectified within the stipulated timeframe of reporting:

S.NO	STATION CODE	STATION	STATE	Date of First Reporting	CORS Continuously Down for Days	Penalty @ Rs. 5000 per day
1	BHUN	BHUNA	HARYANA	22-09-2022	11	55,000
2	PALW	PALWAL	HARYANA	03-10-2022	29	145,000
3	PANI	PANIPAT	HARYANA	13-10-2022	10	50,000
4	NUH	NUH	HARYANA	20-10-2022	12	60,000
5	DELH	DELHIPALAM	DELHI	21-10-2022	11	55,000
6	GOHN	GOHNA	HARYANA	22-10-2022	10	50,000
7	GURG	GURGAON	HARYANA	23-10-2022	9	45,000
8	RMPR	RAMPUR	HIMACHAL	17-10-2022	13	65,000
9	CHPL	CHAUPAL	PRADESH	17-10-2022	13	65,000
10	KAIL	KAILARAS	MADHYA PRADESH	15-10-2022	9	45,000