



Tallis Mechanical Services

Heating, cooling, refrigeration and ventilation | License No. CCB-000000 (placeholder)
1840 SE Division Street, Portland, OR 97202 | (503) 555-0187

JOB SHEET

JOB NO.
WO-2026-0130

SHEET
1

OF
1

1 JOB

VISIT DATE 09/14/2026	ARRIVED 06:45	LEFT 09:00	HOURS ON SITE 2.3
STATUS (OFFICE USE) ☐ Draft ☐ Scheduled ☐ In progress ☒ Completed ☐ Invoiced			

2 CUSTOMER AND SITE

CUSTOMER Ashgrove District Schools	CUSTOMER PO / REFERENCE ADS-PO-2026-311	
SITE ADDRESS Ashgrove Middle School, boiler room 3300 SE Harold St, Portland, OR 97202	SITE CONTACT Ellen Varga	PHONE (503) 555-0172

3 EQUIPMENT

TYPE ☐ Air conditioning ☐ Heat pump ☒ Boiler ☐ Ventilation ☐ Refrigeration ☐ Other			UNDER WARRANTY ☐ Yes ☒ No
MANUFACTURER Caldeira Thermal	MODEL NO. CT-399	SERIAL NO. CT399-150908-0041	INSTALLED 09/08/2015

4 WORK

FAULT REPORTED Boiler 2 locking out on flame failure before school opens. Building below 60 F at 6 am.
WORK PERFORMED Cleaned the flame sensor and replaced it, and replaced the cracked igniter and a worn condensate trap. Test fired ten cycles with no lockout.
OUTCOME ☒ Resolved ☐ Temporary fix ☐ Parts on order ☐ Follow-up visit required
FOLLOW-UP NOTES

5 PARTS AND LABOR

More than six parts? Continue on a continuation sheet.

PART NO.	DESCRIPTION	QTY	UNIT PRICE	LINE PRICE
IGN-399	Hot surface igniter	1	68.00	68.00
FS-12	Flame sensor	1	34.50	34.50
CT-075	Condensate trap assembly	1	52.25	52.25
PARTS TOTAL (\$)	LABOR HOURS	RATE / HR (\$)	LABOR TOTAL (\$)	TOTAL (\$)
154.75	2	120.00	240.00	394.75

6 SIGN-OFF

TECHNICIAN Nadia Sokolov	CUSTOMER SIGNATURE: THE WORK ABOVE WAS CARRIED OUT
PRINT NAME Ellen Varga	DATE 09/14/2026